

**To:** Kamke, Sherry[Kamke.Sherry@epa.gov]  
**From:** Egan, Robert  
**Sent:** Mon 12/14/2015 3:07:41 PM  
**Subject:** FW: Tower Standard  
[40124997\\_frc.pdf](#)  
[40124714\\_frc.pdf](#)

Groundwater data is in the second file. I haven't correlated it with the locations yet, but some is highly contaminated and some much less.

Bob Egan

Corrective Action Manager

Underground Storage Tanks Section

RCRA Branch

EPA Region 5

(312) 886-6212

(312) 692-2911 (fax)


**From:** Dave Larsen [mailto:dlarsen@reiengineering.com]  
**Sent:** Friday, December 11, 2015 2:51 PM  
**To:** Robinson, John H - DNR (John.Robinson@wisconsin.gov)  
<John.Robinson@wisconsin.gov>; Lundquist, Greer I - DNR  
(Greer.Lundquist@Wisconsin.gov) <Greer.Lundquist@Wisconsin.gov>  
**Cc:** Egan, Robert <egan.robert@epa.gov>; KHanson@ldftribe.com  
**Subject:** Tower Standard




Bob, John had asked that I provide concurrent notification on the attached data. REI has completed the well installation, development, sampling and survey of the 14 new wells. Bob the wells were sampled using the same methodology utilized on the Boivin project. I am also in the process of completing the soil boring logs, wells construction forms, well development forms and borehole abandonment forms on the 2 failed attempts to set the piezometers and I am hoping to have them completed today.

Thank you,

David N. Larsen P.G

Hydrogeologist / Professional Geologist



Connect with us :   

*Confidentiality Notice: This message is intended for the recipient only. If you have received this e-mail in error please disregard.*